

## Software Release Note

### **ALT-8015 Radio Altimeter Test Set, Software Version 1.4.5 Release**

This information bulletin is to inform current users of the ALT-8015 that a new version of operational software is now available. The new software can be obtained by contacting the VIAVI Service Department in Wichita, Kansas.

#### **Effectivity**

All ALT-8015 users testing APN-209J/K/L radio altimeters will require this operational software update. Implementation of the software will change the currently installed version to 1.4.5. Recalibration is not required.

#### **Summary of changes**

1. Added test capability for APN-209J/K/L radio altimeter variants
2. Improved Self-Test

#### **Downloading and installing the new software**

Installation of the new software is outlined in the operator's manual 92956 (section 5.2.2). The latest version of the ALT-8015 software is export controlled and can be obtained by contacting VIAVI Solutions and requesting software part number 92879.

#### **Contact information**

VIAVI Solutions  
Avionics and Radio Test  
10200 West York Street  
Wichita, KS 67215  
800-835-2350  
avcomm.service@viavisolutions.com

#### **Document Revision History**

Revision	Date	Reason	ECN
AA	11/30/2016	Release of v1.4.0 software	500000007734
AB	06/08/2017	Release of v1.4.1 software	500000007954
AC	10/12/2018	Release of v1.4.5 software	500000008652